



3 - 380 RIVERSIDE ROAD ♦ ABBOTSFORD, BC V2S 7M4 ♦ (604) 504-5904

SERVICE INVOICE	
R401007472:01	
Date Invoiced:	01/10/2019
PO No:	
Terms:	C-CSH

**BILL TO**  
 CLE CAPITAL - 26895  
 3390 S SERVICE RD SUITE 104  
 BURLINGTON ON L7N 3J5  
 P: (604) 313-5842  
 F:

**DELIVER TO**  
 DON WAINES TRUCKING LTD. - 24848  
 145 - 27111 O AVENUE  
 ALDERGROVE BC V4W 2T8  
 P: (604) 313-5842  
 F:

DATE CREATE	JE ID	ADVISOR	VIN ID	MODEL #	SERIAL #	ORIG. DOCUMENT	SALES TYPE
11/26/2018	655651	EM EM	131879	388	1XPWDB0X79D777495		SRET GST
HOURS	ODOM IN	ODOM OUT	CUSTOMER UNIT #				
0	1038008	1038008	18				

**Sold Operations**

**JOB #1 50-DIAG-ENGI DIAGNOSTICS ENGINE**

**COMPLAINT** REPAIR FOR EXTERNAL COOLANT LEAK AT HEAD GASKET.

**CAUSE**

**CORRECTION** FOUND HEAD GASKET WAS LEAKING EXTERNALLY. DRAIN COOLANT. DISASSEMBLE TOP END, REMOVE TURBO'S, ALL HOSES, WIRING, ETC. REMOVED HEAD AND INSPECT. FOUND # 3 AND #4 LINERS SCUFFED BAD AND THE REMAINING 4 WERE GLAZED. CUSTOMER AUTHORIZED PLATINUM OVERHAUL. DRAINED OIL AND PULLED PAN. REMOVED ALL CYLINDER KITS. CLEANED ALL PARTS AND ROLLED IN MAIN BEARINGS. INSTALL CYLINDER KITS AND MEASURE PROTRUSION, ALL IN SPEC. SWAPP ALL PARTS TO NEW HEAD AND INSTALL WITH NEW BOLTS. INSTALL CAM GEAR AND SET TIMING AS WELL AS BACKLASH TO SPEC. INSTALL NEW INJECTORS AND ASSEMBLE TOP END. PERFORM COMPLETE TOP END SET. INSTALL NEW WATERPUMP AND INSTALL OLD TURBO'S. INSTALL NEW OIL PUMP AND PISTON COOLING NOZZLES. INSTALL OIL PAN WITH NEW SEAL AND ISOLATORS. INSTALL ALL HOSES, WIRING, ETC. FILL WITH OIL AND COOLANT. PROGRAM INJECTORS AND RUN ENGINE. NO LEAKS. TEST DRIVE UNIT TO VERIFY REPAIR, ALL OK.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	401D/23-14393-000	UNION-PTC,,25 NT TO .25 NT	2.88	2.88
2	401D/BRZ 9220H	CLAMP-HOSE,13/16-1 3/4IN,1/2IN	2.16	4.32
2	401D/BRZ 9240H	CLAMP 2 1/16 - 3	2.36	4.72
2	401D/DN P534925	AIR PRMYRS *D	99.18	198.36
3	401D/TYC DCT110HIR	TIE STRAP	1.66	4.98
1	401K/1304698	SLEEVE	65.65	65.65
1	401K/20R7414	PLATINUM KIT (SDP)	18,269.71	18,269.71
-1	401K/20R7414-CORE	PLATINUM KIT (SDP)	8,655.43	-8,655.43
1	401K/20R7414-CORE	PLATINUM KIT (SDP)	8,655.43	8,655.43
1	401K/2147568	SEAL-O RING	6.68	6.68
6	401K/2764637	TUBE AS-OIL	151.75	910.50
1	401K/2877014	HOSE	30.77	30.77
4	401K/2N2766	LOCK NUT	9.63	38.52
1	401K/3097641	HOSE	28.24	28.24



**Sold Operations (Cont.)**

QTY	ITEM	DESCRIPTION		UNIT PRICE	EXTD PRICE
1	401K/3H1461	RING	G	3.41	3.41
2	401K/4795400	CAT YELLOW PAINT	G	17.01	34.02
1	401K/6V5048	SEAL-O-RING	G	5.73	5.73
1	401K/9L8925	BOLT	G	0.31	0.31
1	401K/9S8002	PLUG	G	6.77	6.77
1	401K/9S8004	PLUG	G	11.19	11.19
5	401K/9S8752	NUT	G	0.44	2.20
44	401O/217D7F	15W40 CK-4 CASTROL "CRB" BULK	G	3.78	166.32
1	401X/FV-109-C	SQUARE HEAD PLUG	G	1.42	1.42
1	401X/FV-1460-4	FITTING	G	0.20	0.20
1	401X/FV-1461-4	FITTING	G	0.80	0.80
2	401X/FV-1485-4-100	1/4 TUBE	G	0.70	1.40
2	401X/FV-TS17R-16	CLAMP	G	0.65	1.30
3	401X/ROO-16-834	50/50 EXTENDED LIFE ANTIFREEZE	G	10.99	32.97
	LABOUR EA-001	DIAGNOSTICS ENGINE	G		9,020.00
40	EN0005	ENVIRONMENTAL FEE	G	0.05	2.00
2	EN0025	ENVIRONMENTAL FEE	G	0.25	0.50
3	EN0114	ENVIRONMENTAL FEE	G	1.14	3.42
				Parts: \$19,833.37 Labour: \$9,020.00 [55.00] Misc: \$5.92 Sublet: \$0	\$28,859.29
<b>Sold Operations Sub-Totals</b>				<b>Parts: \$19,833.37 Labour: \$9,020.00 Misc: \$5.92 Sublet: \$0.00</b>	<b>\$28,859.29</b>

If you would like to have your invoices automatically emailed to you, contact our accounts receivable department at AR@cullendiesel.com

YEAR/MAKE/ MODEL: 2009 / PETERBILT / 388
ENGINE MODEL/SERIAL /HRS: C-15 / SDP13360 / 0
TRANS MODEL/SERIAL: /
REAR AXLES MODEL/ SERIAL: /
DATE IN SERVICE:

	ESTIMATED	BILLED
LABOUR		\$9,020.00
PARTS		\$19,833.37
MISC		\$5.92
SUBLET		\$0.00
<b>SUBTOTAL</b>		<b>\$28,859.29</b>

SHOP SUPPLIES \$541.20  
 PST ~~\$37.88~~ **EM**  
 GST/HST 1,470.02  
**TOTAL \$30,908.39**  
**EM \$30,870.50**

*(EM) Customer to pay \$37.88 PST on sepeate transaction.*

AUTHORIZED BY \_\_\_\_\_ DATE \_\_\_\_\_

Please Remit Payment to:  
 CULLEN WESTERN STAR TRUCKS  
 LTD.  
 9300 192ND STREET  
 SURREY, BC V4N 3R8  
 GST NO: 866231756



**CONDITIONS OF WARRANTY AND TERMS OF WORKMANSHIP**

1. Cullen warrants to the original customer only, to correct, subject to the terms set out herein, any defect in workmanship on diesel engines or transmissions, which have been completely rebuilt in Cullen's plant. Such defects must be presented to Cullen within six (6) months from the date of repair of the owners engine or transmission. A similar warranty is hereby given on partial overhauls, minor repairs, or field service provided defects are presented within thirty (30) days of repairs.

2. In the event of any failure on which a warranty claim may be presented, the owner must notify Cullen and follow Cullen's suggestions in connection with the inspection or disposition of the defective part or parts and to the repairing and/or replacement thereof.

3. It is a condition of any applicable warranty that the owner shall:

a) have complied with all service requirements and recommendations of Cullen and/or the manufacturer relating to the equipment;

b) retain any failed part for inspection by Cullen.

4. The warranties are contingent on the proper application of the engines and products by the owner in accordance with the recommendations of product which shall have been repaired, altered or installed in any way so as in the judgement of Cullen to affect adversely its performance and reliability nor which have been subject to misuse, negligence, or accident, or equipment that has been repaired to the customer's specifications rather than to Cullen's recommendations.

5. Cullen's obligation under this Warranty is limited to supplying parts and mechanical labour to correct a defect in workmanship to an amount not exceeding the charges for the original repair and shall not include any transportation charges, loss of revenue or any direct or indirect consequential damages.

6. Cullen shall not be liable for any personal injuries (including death) to any person or any other loss or damage, either direct, indirect or consequential whether to the equipment or to any other property from any cause or reason whatsoever.

7. Cullen shall only be liable under the warranties set out in paragraph 1 hereof if the owner returns the defective equipment to Cullen's shop at the owner's expense, however if the defective equipment was installed by Cullen, Cullen may, at the request of the owner, agree to carry out repairs at some other location provided the cost of Cullen's servicemen's travel time and service truck mileage do not exceed One Hundred Dollars (\$100.00)

8. All warranty work will be done on a straight time basis, customer will be charged for the difference between straight time and overtime and overtime travel.

9. Notwithstanding any other provision hereof the warranties set out in paragraph 1 hereof do not cover:

a) Replacement of service items, engine oil and filters, air and fuel filters, fan and alternator belts, power steering fluids and belts, radiator and heater hoses, engine throttle controls and emergency stop cables, and air conditioning Freon replacement: Antifreeze.

b) overheating of the engine due to shutter control thermostats, air supply and relays, air controlled fan, air or electric or thermo controls, air conditioning override controls and the installation of larger injectors which exceed O.E.M. cooling system ability;

c) any hoisting, trucking or transportation charges, or removal and return of engines or products.

10. Any new parts installed by Cullen are warranted only to the extent of the warranty furnished by the manufacturer of such parts. Parts which are replaced or those which are reused and any workmanship not affected by repair are warranted only to the extent of any previously existing warranties.

11. Notwithstanding any other provisions hereof Cullen shall incur no liability for inspection of any equipment or service work performed to determine the condition of any equipment and Cullen shall not be liable for any damages suffered by any customer or other person relying upon an inspection report done by Cullen.

12. Cullen shall incur no liability for any delay or failure to perform any of its obligations hereunder by reason of strike, threat of strike, lockout, fire, flood, interruption, or delay in manufacture or transportation, act of nature, war, insurrection, mob violence, requirement of governmental authorities, embargo, shortage of labour, equipment or materials, plant breakdown, or any other causes beyond the control of Cullen whether or not such causes of delay or failure are in existence at the time of acceptance of this work order.

13. Prices for service are subject to change without notice in accordance with increases in parts prices, adjustments in exchange rates, increases in freight, duty or brokerage rates, or Cullen's labour rates. The owner agrees with Cullen to pay the prices effective during the period of repair.

14. A lien may be placed on any equipment repaired pursuant to the terms hereof which lien shall subsist until all indebtedness and all sums due or to become due from the owner shall have been fully paid.

15. This Warranty and these terms of workmanship shall be construed by and in accordance with the laws of the Province of British Columbia.

16. The entire liability and obligation of Cullen with respect to workmanship is defined by this warranty and is given in lieu of any and all other warranties expressed or implied. No oral or written statements or representations with respect to the subject matter hereof shall be binding unless endorsed hereon. Upon the expiration of this warranty all liability on the part of Cullen in connection therewith shall terminate in any event.

17. Parts are covered only to the extent of the Manufacturer's Warranty.

18. "Over-The-Counter" Sales - Labour costs for part removal, repair and reinstallation, or progressive damage to other engine parts are not covered when the Part was purchased "over-the-counter" and installed by other than an authorized service outlet.