

TRUCK / TRAILER CONDITION REPORT
CLE/HITACHI CAPITAL
3390 SOUTH SERVICE ROAD, SUITE 301
BURLINGTON, ON L7N 3J5
ATTENTION: GUNTHER BOENISCH TEL:866-241-9021 EXT 2103

Client Name:			
Attention:			
Our File #			
Customer			
Lease #			
Located at			
Repossession Date :	D	M	Y
N.O.I. Date:	D	M	Y
Appraisal Date:	D	M	Y 25/07/2020.
Type of Unit	<input checked="" type="checkbox"/> Truck <input type="checkbox"/> Trailer		
Type of Truck or Trailer			
Make	Volvo		
Year	2019		
Model	VNL 740		
Color	Exterior: white Interior: Grey		
Plate #	Expires D M Y		
Serial #			
Mileage	<input checked="" type="checkbox"/> Km <input type="checkbox"/> Miles 249837		
Hours	4143 4143 hours		
Warranty (Describe)	<input type="checkbox"/> Y <input type="checkbox"/> N		
Wheelbase	Inches		
Sleeper	73" <input type="checkbox"/> With bunk bed(s)		
Motor	6 Cylinder <input checked="" type="checkbox"/> 013		
Fuel Type:	<input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Gas <input type="checkbox"/> Propane		
Horsepower	500 hp		
Engine Brake	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
Transmission	I shift <input checked="" type="checkbox"/> Auto <input type="checkbox"/> 18spd <input type="checkbox"/> 15 Spd <input type="checkbox"/> 13 Spd <input type="checkbox"/> 10 Spd		
Options	<input type="checkbox"/> Headache Rack <input type="checkbox"/> PW <input checked="" type="checkbox"/> PL <input checked="" type="checkbox"/> PM <input type="checkbox"/> A/C <input type="checkbox"/> Power Sunroof <input checked="" type="checkbox"/> Tilt <input checked="" type="checkbox"/> Cruise <input checked="" type="checkbox"/> AM/FM <input type="checkbox"/> Cassette <input checked="" type="checkbox"/> CD <input type="checkbox"/> Nav <input type="checkbox"/> GPS <input type="checkbox"/> Satellite Radio		
Exterior Condition	Windshield: <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor		
	Other Glass: <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor		
	Body Condition: good, small damage on bumper plastic.		

TRUCK / TRAILER CONDITION REPORT

Interior Condition		Seats: <input checked="" type="checkbox"/> Cloth <input type="checkbox"/> Leather <input type="checkbox"/> Vinyl											
		Seats: <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor											
		Carpet: <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor											
		Interior Condition:											
Running Condition		<input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor											
Suspension		Air											
# Of Axles		3											
Front Axle (Lbs)		13200.											
Centre Axle (Lbs)													
Rear Axle (Lbs)		46000.											
Ratio		3.58.											
Suspension Spread		Inches 55.											
		Outside Left			Inside Left			Inside Right			Outside Right		
		Size	Al	St	Size	Al	St	Size	Al	St	Size	Al	St
Tire Size and Rim Type	Front	245	<input checked="" type="checkbox"/>	<input type="checkbox"/>	N/A	-	-	N/A	-	-		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Center Lift		<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>
	Rear 1		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Rear 2		<input checked="" type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Rear 3		<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>
	Rear 4		<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>
		Outside Left			Inside Left			Inside Right			Outside Right		
Tire Percentages	Front	50	%		N/A			N/A			50	%	
	Center Lift		%		%			%			%		
	Rear 1	50	%		50	%		50	%		50	%	
	Rear 2	50	%		51	%		50	%		50	%	
	Rear 3		%		%			%			%		
	Rear 4		%		%			%			%		
Trailer Length		Feet											
Trailer Width		Inches											

TRUCK / TRAILER CONDITION REPORT

General Comments

Mechanical Condition:	<input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor
Overall Condition:	<input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor

Auction Values as of M Y


Extra Clean	\$	
Clean	\$	80 K.
Average	\$	
Rough	\$	

ESTIMATED VALUE RETAIL	RESALE	
ESTIMATED RESLE VALUE AS IS		

This unit will need the following repairs done in order to resell: (you may include attachments for quotes and costs)

- repair cracked side panel passenger side.

Other notes regarding this unit:

Condition Report Taken By:	Date of Condition Report: D M Y <i>25/03/20.</i>
Pictures Taken: <input checked="" type="checkbox"/> Y <input type="checkbox"/> N	Date Pictures Taken: D M Y
Registration: <input type="checkbox"/> Y <input type="checkbox"/> N	Keys: <input checked="" type="checkbox"/> Y <input type="checkbox"/> N
Insurance Claim: <input type="checkbox"/> Y <input type="checkbox"/> N	
Fluid Check: <input type="checkbox"/> Motor <input type="checkbox"/> Transmission <input type="checkbox"/> Brake <input type="checkbox"/> Coolant	
Date personals removed and inventoried: D M Y	
Condition Report Completed by:	
 D M Y <i>25/03/20.</i>	